


Sağ Taraf 2. Test Sonrası		A	B	C	D	E	F	Toplam
Hata Görülmemiş Borular	○	152	168	291	164	133	69	977
% 20 den az hatalı Borular	●	0	7	2	55	2	8	74
% 50 den az hatalı Borular	●	12	2	13	36	35	59	157
% 50 den fazla hatalı Borular	●	44	6	29	6	43	21	147
Delik – Çatlak Borular	●	1	3	1	7	17	15	44
Dış- Çatlak Borular	●	0	11	0	0	0	0	11
Tıkalı Borular	●	7	127	194	258	92	41	719
Önceden körlenmiş Borular	●	4	5	0	5	0	5	21
Toplam :		220	329	530	531	322	218	2,150



A

B

C

D

E

F

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84

1 2 3 4 5 6 7 8 9 10 11 12

13 14 15 16 17 18 19 20 21 22

23 24 25 26 27 28 29 30

31 32 33 34 35 36 37

38 39 40 41 42 43 44

45 46 47 48 49 50 51 52

53 54 55 56 57 58 59 60

61 62 63 64 65 66

67 68 69 70 71 72

73 74 75 76 77 78 79 80

81 82 83 84 85 86 87

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87